# **Holder Services**

The Knife Holder consists of 2 major components. The control body which connects the holder to the dovetail and the blade cartridge which holds the top slitter knife. Each rebuild includes inspection, lubrication and replacement of the standard wear parts. These wear parts will be sent back to the company upon request.

### **Holder Models Serviced**

#### **MARIO COTTA**

Tiny PPJ

Silver

PPS

Classic Series

Rocky

Gold

Platinum Models

#### **TIDLAND PERFORMANCE SERIES**

Class I

Class II

Class III

#### **TIDLAND "C Series" KNIFEHOLDER**

\*Spare/Replacement Parts are Limited in C Series

Class I

Class II

Class III

## Clean, Inspect, Calibrate, and Replace Standard Wear Parts

Mario Cotta @ \$395.00 each Tidland @ \$350.00 each

Any additional parts outside the wear parts kit that are worn and need to be replaced will be completed on a time and material basis. When this cost reaches 50% or greater than the cost of a new knife holder, the customer will be notified to determine how they would like to proceed. If the decision to order new holders is made by the customer, a \$125 fee will be charged for the breakdown and inspection of the holder's condition. If the customer agrees for the repairs, the \$125 will be waived.

If an estimate of repair is required prior to rebuilding, a \$125 fee per each assessment will apply. If the customer agrees to continue with the rebuild, the fee is waived.

#### **Turnaround Times:**

**Assessment:** 1-2 weeks determined by the total number of holders needing assessment **Rebuilds:** 2-3 weeks determined by all stock parts being on hand

**Non-Stock/Standard Wear Parts Replacement**: Determined after needed parts are determined **Wear Parts:** O-Rings, Springs, Bearings, Bellows, Air Lines

Certified Tested Components: 55 PSI, Cant Key °, T.I.R., Air Leaks, Horizontal/Vertical Motion

